Jubilee Bridge

June 2018

| Recommended work 2018/19 | Estimated cost £ | Repeat | 20 yr cost | Notes |
|---|------------------|-----------------|-------------|---|
| Clean bridge steelwork and decking | £5,000.00 | 6yr intervals | £15,000.00 | Not done for 16yrs |
| Replace rotten handrails with stainless | £9,500.00 | Never | £9,500.00 | Broken and rotten in parts. Suggest replace with stair |
| Lighting - LED | £10,000.00 | 20 yrs. | £10,000.00 | Vandalised repeatedly,footlights are not working,upli |
| Decking repairs | £5,000.00 | 10 yr intervals | £10,000.00 | Generally ok but loose and moving in parts, antislip st |
| Decoration | £4,000.00 | 6 yr intervals | £12,000.00 | Touch up along whole bridge especially at low level, i |
| ССТV | £3,000.00 | 10 yrs | £6,000.00 | |
| | £36,500.00 | | £62,500.00 | |
| Recommended Annual Maintenance | | | 20yr cost | |
| General repairs graffiti cleaning and vandalism | £1,000.00 | | £20,000.00 | |
| Lighting repairs | £800.00 | | £16,000.00 | Blown lamps and vandalism |
| Timber decking repairs | £500.00 | | £10,000.00 | General wear and tear |
| antislip strip repairs | £500.00 | | £10,000.00 | General wear and tear |
| | £2,800.00 | | £56,000.00 | |
| Other maintenance | | | | |
| Tie rods, support mast and upper structural members | £5,000.00 | 10 yr intervals | £10,000.00 | Attend to surface corrosion, apply anti corrosion |
| Painting & decorating complete structure | £10,000.00 | 10 yr intervals | £20,000.00 | Possibly not been decorated for 16 yrs? |
| | £15,000.00 | | £30,000.00 | |
| | | | | 1 |
| Inspections | | | | |
| Principal inspection - NB carried out May 2018 | £1,500.00 | 6yr intervals | £6,000.00 | |
| General inspection | £250.00 | 2 yr intervals | £1,500.00 | |
| | £375.00 | av/yr | £7,500.00 | |
| Estimated expenditure 2018 - 2038 | | | £156,000.00 | 20 year costs exclude indexation |
| | | | | |
| | | | | |

Note

1 NCC indicated a dowry of approx £430,000 required for the lifetime of asset. If this is assumed as a 60 year life, there are approx 44 years remaining.

£9,800.00

2 That equates to an approximate sum per annum of

3 Our estimate shows an average spend per annum of £7,800.00 if all items were carried out as indicated in table

4 This does include enhancement (lighting and CCTV) to benefit tourism plan and improvements to this area

5 Excludes unforseens - eg foundation deterioration (but no evidence of this)

6 Regular maintenance will minimise/remove major expenditure items

7 Future year costs exclude indexation

| Recommended Annual Maintenance | | |
|---|------------|-----------|
| General repairs graffiti cleaning and vandalism | £1,000.00 | |
| Lighting repairs | £800.00 | |
| Timber decking repairs | £500.00 | |
| antislip strip repairs | £500.00 | |
| | | £2,800.00 |
| Inspections | | |
| Principal inspection - NB carried out May 2018 | £1,500.00 | £1,500.00 |
| Recommended Work 2018/2019 | | |
| - | | |
| Clean bridge steelwork and decking | £5,000.00 | |
| Replace rotten handrails with stainless | £9,500.00 | |
| Lighting - LED | £10,000.00 | |
| Decking repairs | £5,000.00 | |
| Decoration | £4,000.00 | |
| CCTV | £3,000.00 | |
| | | £36,500.0 |
| Other maintenance | | |
| Tie rods, support mast and upper structural members | £5,000.00 | |
| Painting & decorating complete structure | £10,000.00 | |
| | | £15,000.0 |

ainless steel handrails (vandal proof fixings to avoid theft)

plighters cage is rusted lights vandalised

strips missing, broken timbers

I, including surface corrosion on steel, plus concrete work areas.