Schedule of Condition

Date: 28/11/2022

Address: Unit 2, Church Farm Business Centre, Edwinstowe, NG21 9NU

Page: 1 of 4

Tenant:



Front elevation

Front Elevation Internal



East Wall Internal



North Wall Internal



West Wall Internal

Kitchenette South



Kitchenette North



Toilet North



Toilet South



Passage to East



Passage to West



Distribution Board 1



Electrics



Distribution Board 2



Meter Read 28 11 22 04862 kWh

Notes: insert additional sheets as required

The unit is in good condition both internally and externally. There is some localised damp (not serious) that has lifted the emulsion paint from walls. Where the new radiators have been fitted (2022) requires painting behind. There is some minor filling required to the front door where a Ring type door bell system has been removed. The extractor in the kitchen is fully functional, as are the water heaters in the kitchenette and toilet. It is noted that some of the light fittings require new lamps and these will be replaced by the landlord before handover. New electric radiators were fitted in 2022, the tenant will be provided with an instruction booklet.

The electric meter reading was noted ats 04862, this, along with the water meter reading will be captured on date of handover.

Schedule of condition prepared by:	Schedule of condition agreed with:
Name Peter Preece	Name:
Position Estates Manager	Signed:
Newark and Sherwood District Council	On behalf of:
	Date